

CLASSIFIED MESSAGE

DATE

0906Z 09 SEP 63

SECRET

ROUTING	
1	OD
2	5
3	6

Comms
DEA
Int'l
RB

TO : DIRECTOR

FROM :

[Redacted]

ACTION:

INFO : OSA 1-15

Mission 6066

ROUTINE

EDD	
WER	
RDO	
RLP	
KB	
SHI	
PGS	

IN 90462

TOR: 1156Z 09 SEP 63

TO

[Redacted]

INFO

CITE

0350

REF 2600

TECH ANALYSIS OF [Redacted] DUPE OF MISSION 6066

1. TRACK-1 RCVR B-SCAN APPEARS NORMAL EXCEPT FOR BEGINNING AND END OF MISSION. NUMEROUS INTERCEPTS AT BOTH THESE POINTS, SWEEP AND RETURN TIME APPEARED NORMAL ON SCOPE, BUT WAS SLIGHTLY AFFECTED BY SPURS.

TRACK-2 RCVR A-THIS RCVR HAD A FAILURE IN THAT THE MARKER PULSES PRODUCED WERE DISTORTED. NUMEROUS INTERCEPTS AT BEGINNING AND END OF MISSION. CAN UNDERSTAND ODINCH DIFFICULTY IN FREQ READOUT DUE TO DISTORTION OF MARKER PULSES.

TRACK-3 RCVR C-SCAN APPEARS NORMAL, 3.5 MS SWEEP, 3.0 MS RETURN, ACTIVITY MUCH THE SAME AS TRACK-1.

2. THE SYSTEM FLOWN ON THIS MISSION (SER 5) SCHEDULED TO BE LOADED ON NEXT TRAINING FLIGHT. WILL CHECK TAPE AND NOTIFY HQS OF ANY DEVELOPMENTS.

END OF MESSAGE

25 YEAR RE-REVIEW

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

7